



Greene Farms 6 & 7 Homeowners Association
P. O. Box 970385
Ypsilanti, MI 48197
greenefarms6and7@yahoo.com

SIDEWALK:

It is in the best interest of Greene Farms 6 & 7 Homeowners Association to correct sidewalks that are a trip hazard. Residents who have sidewalk complaints are directed to contact Greene Farms 6 & 7 Homeowners Association at the above mailing address or via email. The resident's report will then be added to our list for inspection and will be handled on the specifics of each complaint.

In an effort to align the association's guidelines with The Charter Township of Ypsilanti the following guidelines are in place to address sidewalk repairs;

Sidewalk Repair Guidelines:

- Sidewalk must be two (2) or more inches misaligned with adjacent sidewalk panel.
- Cracked sidewalk panels must have two (2) or more inches misalignment.

(Sidewalk panels that adjoin the homeowner's driveway will be considered on a case by case basis in conjunction with services Homeowner is having done at the same time).

Each summer we will review the services that have been requested, and if repairs are needed. There are many factors involved including, weather, funding, time and conditions of the existing sidewalk.

MAILBOX AND MAILBOX POST:

Mailboxes and Mailbox Posts are the property and responsibility of Greene Farms 6 & 7 Homeowners Association. In an effort to make all streets uniformed in style and appearance we ask that you do not alter, remove or change any Mailbox or Mailbox Post. All Mailbox Posts are to be black in color and the bottom six (6) inches are to be covered with copper. All Mailboxes are constructed of metal and black in color. Mailboxes will have address labels located on the front of Mailbox; decals will have numbers and letter in the color of bronze, and a background color of black. If there are any service requests that are required for your Mailbox or Mailbox Post contact Greene Farms 6 & 7 Homeowners Association at the above address or via email. There are many factors involved in service request including, weather, funding, time, and conditions of the existing Mailbox and Mailbox Post.